


1st Step: Find Included angles as shown

$$180^\circ - 45^\circ = 135^\circ$$

$$180^\circ - 26^\circ = 154^\circ$$

$$180^\circ - 64^\circ = 116^\circ$$



Sample Part
Cutterc2.DWG

4-23-98