



3rd Step: Draw triangles w/ knowns & calculate unknown side



Sample Part

Cutterc4.DWG

4-24-98